


Model Identification For Triumph Tiger 1200 (2022 Onwards)

We have received numerous reports of fitting problems with Tiger 1200 models from (2022 onwards), and have found motorcycles, regardless of year model, may have different handlebar positions in upper triple clamps which is effecting fitment.

Below is information on the different positions and how to identify the correct hardware kit for each model.

Handlebar positioned to the rear of the upper triple clamp

Correct fitment is BHG-101-01-NP



Handlebar positioned to the front of the upper triple clamp

Correct fitment is BHG-102-00-NP

